Office Sub Division Engineer, Construction Sub Division No. 2, Public Works Department, Bhavan Marg Branch, District Administrative Complex, Block: Chenab-Jhelum, 4th Floor, Moga.

To,

Principal
Akal Academy
Kaleke, Distt. Moga.

No. 52 Date: 26.4.2.22

Subject: - Regarding the building safety certificate for the year 2022-2023 Letter No. AAKKI22 dated 08.04.2022

The above building has been inspected by the concerned Junior Engineer and the building has been found safe for 2022-23. Further attention should be paid to the following instructions:

1. Water should not be allowed to stand around the building and on the roofs.
2. If any kind of crack occurs in the building then the place should be vacated immediately and It should be repaired immediately.
3. The responsibility of the material used in any type of construction will be the responsibility of the concerned school, apart from the map attached by you, if you want to do additional construction, then the permission should be taken from this department.
4. As per Director Journal School Education Department Punjab and State Project Sarv Shiksha Abhiyan letter No. 75444 dated 06.11.2009 fire extinguishers should be kept in working condition in the school, all the responsibility of any untoward accident will be with the school concerned.
5. Be sure to conduct inspection next year 2023-24.

Attached: Certificate

NOTARY Suresh Goyal Notary Public Area Distt. Moga Regd No. 587 GOVT. OF INDIA

Certify That it is a True & Correct Translation in English/..... of The Document Produced Before me in Punjabi/.....Script

Suresh Goyal
Notary Public
Distt. Moga
Regn. No. 587

22 SEP 2022

Sub Division Engineer,

Construction Sub Division No. 2, B&M Branch,

Moga

ਦਫ਼ਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 2, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,

ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਜ਼ਿਲ੍ਹਾ ਪ੍ਰਬੰਧਕੀ ਕੰਪਲੈਕਸ, ਬਲਾਕ:ਚਨਾਬ-ਜੇਹਲਮ, ਚੌਥੀ ਮੰਜ਼ਿਲ, ਮੋਗਾ।

ਵੱਲ,

Principal,
Akal Academy ,
Kaleke , Distt. Moga.

ਨੰਬਰ: 52 ਮਿਤੀ: 26.4.2022

ਵਿਸ਼ਾ:- ਇਮਾਰਤ ਸੁਰੱਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਬਾਬਤ ਸਾਲ 2022-2023

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ **AAKK/22** ਮਿਤੀ 08.04.2022

ਉਪਰੋਕਤ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਸਬੰਧਤ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ 2022-23 ਲਈ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ ਹੈ। ਅੱਗੇ ਤੋਂ ਹੇਠ ਲਿਖੀਆਂ ਹਦਾਇਤਾਂ ਵੱਲ ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ:-

1. ਬਿਲਡਿੰਗ ਦੇ ਆਲੇ-ਦੁਆਲੇ ਅਤੇ ਛੱਤਾਂ ਉਪਰ ਪਾਣੀ ਨਾ ਖੜ੍ਹਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
2. ਜੇਕਰ ਇਮਾਰਤ ਵਿੱਚ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸ ਦੀ ਰਿਪੇਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ।
3. ਕਿਸੇ ਕਿਸਮ ਦੀ ਉਸਾਰੀ ਵਿੱਚ ਵਰਤੇ ਗਏ ਮਟੀਰੀਅਲ ਦੀ ਜ਼ੁੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ, ਆਪ ਵੱਲੋਂ ਨੱਥੀ ਕੀਤੇ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨ ਹੋਵੇ ਤਾਂ ਉਸ ਦੀ ਮੰਨਜ਼ੂਰੀ ਇਸ ਮਹਿਕਮੇ ਤੋਂ ਲਈ ਜਾਵੇ।
4. ਡਾਇਰੈਕਟਰ ਜਰਨਲ ਸਕੂਲ ਸਿੱਖਿਆ ਵਿਭਾਗ ਪੰਜਾਬ ਅਤੇ ਸਟੇਟ ਪ੍ਰੋਜੈਕਟ ਸਰਵ ਸਿੱਖਿਆ ਅਭਿਆਨ ਦੇ ਪੱਤਰ ਨੰਬਰ 75444 ਮਿਤੀ 06.11.2009 ਮੁਤਾਬਿਕ ਸਕੂਲ ਵਿੱਚ ਅੱਗ ਬੁਝਾਉਣ ਵਾਲੇ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿੱਚ ਰੱਖੇ ਜਾਣ, ਕਿਸੇ ਵੀ ਅਣਸੁਖਾਵੀ ਦੁਰਘਟਨਾ ਦੀ ਸਾਰੀ ਜ਼ਿੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।
5. ਅਗਲੇ ਸਾਲ 2023-24 ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਕਰਾਉਣੀ ਯਕੀਨੀ ਬਣਾਈ ਜਾਵੇ।

ਨੱਥੀ: ਸਰਟੀਫਿਕੇਟ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 2, ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮੋਗਾ।