

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਸੰਗਰੂਰ।

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,  
ਅਕਾਲ ਅਕੈਡਮੀ (ਅੰਗਰੇਜੀ ਮਧਿਅਮ),  
ਚੀਮਾਂ, ਜਿਲ੍ਹਾ ਸੰਗਰੂਰ।

ਨੰਬਰ

569

ਮਿਤੀ 1-4-2022

ਵਿਸ਼ਾ

ਸਾਲ 2022-23 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:

ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: AAC/EM/04/2022, ਮਿਤੀ 15.03.2022

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਲੋੜੀਂਦੀ  
ਇੰਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ  
ਜੀ। ਲੋੜੀਂਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 5000/- ਜੀ.ਆਰ ਨੰ: 663693 ਮਿਤੀ 1-4-2022  
ਰਾਹੀਂ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਨੱਥੀ / ਸਰਟੀਫਿਕੇਟ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ  
ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪਿੱਠ ਅੰਕਣ ਨੰ: 10037 ਮਿਤੀ 25-03-2022 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ  
ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,  
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਸੰਗਰੂਰ।

*[Signature]*

*[Signature]*  
Principal  
Akai Academy, Chasma, Sangrur  
C.B.S.E. Affiliation No. 1630231



## Part-II

### Building Safety Report

Name of School: Akal Academy Cheema (English Medium), Tehsil Sunam,  
(Distt. Sangrur).

I have visited the above-mentioned School Building along with Sh. Varinder Kumar / Junior Engineer and on visually inspection; it seems visually safe subject to the following observation & conditions.

- Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
- A separate certificate regarding Electrical works should be obtained from the competent Authority.
- The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- The covered area of the building is As per Drawings Sft.
- The report is not valid for legal purpose.
- The building visually seems safe to occupy for normal use to **One Year, upto 31/03/2023**

(Provincial)

Serial No. Y

666663

1.4.2022

Received from Baldev Singh

with letter No. 10037 dated 25.1.2022

the sum of Rupees 5000/-

In Cash by Cheque on account of 5000/-

In Handwritten payment of 5000/-

Rs. 5000/- Signature 20.22.23

Sub Divisional Engineer  
Sangrur Sub Division P.W.D.  
SANGRUR (P.D.)

Sub Divisional Engineer  
Sangrur Sub Division P.W.D., B&R  
Sangrur Sub Division P.W.D.  
B & R

Principal

Akal Academy, Cheema, Sangrur  
C.B.S.E. Affiliation No. 1630231