

ਦਫਤਰ: ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ
(ਭਵਨ ਤੇ ਮਾਰਗ)ਸ਼ਾਖਾ ਟਾਂਡਾ।

ਵੱਲ

ਹੈਡਮਿਸਟਰੈਸ
ਅਕਾਲ ਅਕੈਡਮੀ,
ਪੁੱਗਾਂ ਕਲਾਂ, ਤਹਿ ਦਸੂਹਾ
ਜਿਲ੍ਹਾ ਹੁਸ਼ਿਆਰਪੁਰ।

ਨੰਬਰ: 455

ਮਿਤੀ: 16-12-2022


ਵਿਸ਼ਾ:- ਇਸੂ ਆਫ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਫਾਰ ਦੀ ਯੀਅਰ 2023-27.

ਹਵਾਲਾ : ਆਪ ਦਾ ਪੱਤਰ ਨੰ. AADHK/58/769/3/Gen. Letter, ਮਿਤੀ 08-12-2022

ਉਪਰੋਕਤ ਸਕੂਲ ਦੀ ਇਮਾਰਤ ਦਾ ਨਿਰੀਖਣ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਸਾਲ 2023-27 ਲਈ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ ਹੈ, ਪ੍ਰੰਤੂ ਹੇਠ ਲਿਖਿਆ ਹਦਾਇਤਾ ਵੱਲ ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ।

1. ਬਿਲਡਿੰਗ ਦੇ ਆਲੇ-ਦੁਆਲੇ ਅਤੇ ਛੱਤਾਂ ਉੱਤੇ ਪਾਣੀ ਖੜਾ ਨਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
2. ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੇ ਕਿਸੇ ਹਿੱਸੇ ਕਿਸੇ ਕਿਸਮ ਦੀ ਤਰੇੜ ਬਗੈਰਾ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਉਸਦੀ ਰਿਪੋਅਰ ਤੁਰੰਤ ਕਰਵਾਈ ਜਾਵੇ।
3. ਬਿਲਡਿੰਗ ਦੀ ਉਸਾਰੀ ਵਿੱਚ ਵਰਤੇ ਗਏ ਮਟੀਰੀਅਲ ਦੀ ਜੁੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।
4. ਨਾਲ ਨੱਥੀ ਨਕਸ਼ੇ ਤੋਂ ਇਲਾਵਾ ਜੇਕਰ ਆਪ ਵਲੋਂ ਕੋਈ ਵਾਧੂ ਉਸਾਰੀ ਕਰਨੀ ਹੋਵੇ ਤਾਂ ਉਸਦੀ ਮੰਨਜ਼ੂਰੀ ਮਹਿਕਮੇ ਪਾਸੋਂ ਲਈ ਜਾਵੇ।
5. ਸਕੂਲ ਵੱਲੋਂ ਬਣਦੀ ਫੀਸ ਜੀ.ਆਰ ਨੰ: 1941143 ਮਿਤੀ: 16-12-2022 ਰਾਹੀਂ ਰੁਪਏ 40,000/- ਜਮ੍ਹਾਂ ਕਰਵਾ ਦਿੱਤੀ ਗਈ ਹੈ।

ਨੱਥੀ/ਨਕਸ਼ਾ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:(ਭ ਅਤੇ ਮ) ਸ਼ਾਖਾ
ਟਾਂਡਾ

ਪਿੱ.ਅੰ. ਨੰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਮੰਡਲ ਨੰ 1 ਲੋ.ਨਿ.ਵਿ.(ਭ ਅਤੇ ਮ) ਸ਼ਾਖਾ ਹੁਸ਼ਿਆਰਪੁਰ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਹੈ ਜੀ।


Principal
Akal Academy
Dhugga Kalan (Hoshiarpur)


Manager
Akal Academy
Dhugga Kalan


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ:(ਭ ਅਤੇ ਮ) ਸ਼ਾਖਾ
ਟਾਂਡਾ।

TRANSLATION FROM PUNJABI TO ENGLISH

Office:- Sub Division Engineer Construction Sub Division Public Works Department
(Building and Passage) Branch Tanda.

To

**Headmistress
Akal Academy
Dhugga Kalan, Tehsil Dasuya,
District Hoshiarpur.**

Number: 455

Date: 16-12-2022




Subject:- Issue of Building Safety Certificate for the year 2023-27.

Reference:- Your letter no. AADHK/58/769/3/Gen.Letter, dated 08-12-2022

That the inspection of the above said school's building by this office and this building was found safe for the year 2023-27, but special attention should be the following instructions :-

1. The water should not be allowed to stand around the building and on the roofs.
2. If any part of the building is exposed to any kind of cracks, the area should be vacated immediately and repaired immediately.
3. That the material used in the construction of the building shall be the responsibility of the concerned school.
4. Apart from the attached map, if any additional construction is to be done by you, then its approval should be taken from the department.
5. Rs. 40,000/- has been deposited by the school through G.R. No. 1941143 dated 16-12-2022.

Attached/Map



Sd/-
Sub Division Engineer
Construction Sub Division P.W.D. (B and P) branch
Tanda

Dispatched No:

Date:

A copy of the above has been sent for information to the Executive Engineer Construction Division No. 1 P.W.D. (B and P) branch Hoshiarpur.

TRANSLATION DOCUMENT ATTESTED


NOTARY, JALANDHAR (PB)

17 DEC 2022

Sd/-
Sub Division Engineer
Construction Sub Division P.W.D. (B and P) branch
Tanda

