

BUILDING SAFETY CERTIFICATE

Certified that the existing building Akal Academy Bakarwal at Village-Bakarwal, Tehsil Dharmkot, District Moga, Pin: 142042, Punjab comprises of only 1 block 0 basements and 2 (Upper floors) owned/occupied by The Kalgidhar Trust, Baru Sahib (H.P.) have complied with the Building Safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of P.W.D. Branch-Moga on 13-04-2023 in the presence of (Principal) Akal Academy Bakarwal and that the building/premises is fit for occupancy upto classes (XII) with effect from 01.04.2023 to 31.03.2028 for a period of five year in accordance with rule and subject to compliance of the specific conditions as appended. The fees for the same as per Govt. guidelines vide G.R. No.5818418 dated 28/04/2023 amounting to Rs.50000/- has been submitted.

The inspection of the above said school's building was done by this office and this building was found safe for the year 2023-28, but special attention should be given on the following instructions :-

1. The water should not be allowed to stand around the building and on the roofs.
2. If any part of the building is exposed to any kind of cracks, the area should be vacated immediately and repaired immediately.
3. That the material used in the construction of the building shall be the responsibility of the concerned school.
4. Apart from the attached map, if any additional construction is to be done by you, then its approval should be taken from the department.

Original Certificate issued on 09/05/2023 at P.W.D. Branch-Moga.

Attached/Map

JE
10/5


Sub Divisional Engineer,
Provincial Sub Division,
P.W.D. Branch-Moga
Provincial Sub Division, P.W.D
(B & R) Branch-Moga (Punjab)



ਦਫ਼ਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,

ਭਵਨ ਤੇ ਮਾਰਗ ਸਾਖਾ, ਮੋਗਾ

Email: sdepsdmogapwdpb@gmail.com

4

ਵੱਲ,

Principal,
Akal Academy
Bakarwala. Distt, Moga.

ਨੰਬਰ 107 ਮਿਤੀ 29/05/2023


ਵਿਸ਼ਾ :- ਇਮਾਰਤ ਸੁਰੱਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਬਾਬਤ ਸਾਲ 2023-2024

ਹਵਾਲਾ :- ਆਪ ਦਾ ਪੱਤਰ ਨੰ: AAB/414/2023 ਮਿਤੀ 03-04-2023

ਉਪਰੋਕਤ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਸਬੰਧਤ ਜੇ.ਈ. ਵੱਲੋਂ ਕੀਤਾ ਗਿਆ ਅਤੇ ਇਹ ਬਿਲਡਿੰਗ ਸਾਲ 2023-24 ਲਈ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ ਹੈ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੁਰੱਖਿਅਤ ਹੋਣ ਸਬੰਧੀ ਸਰਟੀਫਿਕੇਟ ਆਪ ਨੂੰ ਮਿਤੀ 31-03-2028 ਤੱਕ ਦਾ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਹੈ। ਅੱਗੇ ਤੇ ਹੇਠ ਲਿਖੀਆਂ ਹਦਾਇਤਾਂ ਵੱਲ ਵਿਸ਼ੇਸ਼ ਧਿਆਨ ਦਿੱਤਾ ਜਾਵੇ :-

- 1 ਜੇਕਰ ਇਮਾਰਤ ਵਿਚ ਕੋਈ ਤਬਦੀਲੀ/ਵਧਾਇਆ ਜਾਂ ਘਟਾਇਆ ਜਾਂਦਾ ਹੈ ਤਾਂ ਕੰਮ ਕਿਸੇ ਤਕਨੀਕੀ ਇੰਜੀਨੀਅਰ ਦੀ ਦੇਖ ਰੇਖ ਵਿਚ ਹੀ ਕਰਵਾਇਆ ਜਾਵੇ, ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਨਿਮਨ ਹਸਤਾਖਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।
- 2 ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਧਾਂ, ਨੀਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫਤ ਕਰਕੇ ਬੈਠ ਜਾਣ ਅਤੇ ਇਸ ਸੂਰਤ ਵਿਚ ਨਿਮਨ ਹਸਤਾਖਰ ਨੂੰ ਫੌਰੀ ਤੌਰ ਤੇ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿਚ ਲਿਆ ਜਾਵੇ ਜੀ।
- 3 ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੋਅਰ ਹਰ ਸਾਲ ਕਰਵਾਈ ਜਾਵੇ। ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਪੱਖੋਂ ਸੇਫਟੀ ਦੀ ਸਾਰੀ ਜਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਸੰਸਥਾ/ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।
- 4 ਉਕਤ ਸਕੂਲ ਵਿਚ ਲੱਗੇ ਅੱਗ ਬੁਝਾਊ ਯੰਤਰ ਸਬੰਧੀ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਹਰ ਸਾਲ ਸਬੰਧਤ ਦਫਤਰ ਤੋਂ ਲੈਣ ਦੀ ਜਿੰਮੇਵਾਰੀ ਆਪ ਦੇ ਸਕੂਲ/ਸੰਸਥਾ ਦੀ ਹੋਵੇਗੀ।
- 5 ਇਹ ਸਰਟੀਫਿਕੇਟ ਕਿਸੇ ਵੀ ਲੀਗਲ ਕੇਸਾਂ ਲਈ ਪ੍ਰਮਾਣਿਤ ਨਹੀਂ ਹੋਵੇਗਾ।
- 6 ਨਿਮਨ-ਹਸਤਾਖਰ ਉਕਤ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ 2023-2024 ਸਮੇਂ ਵੀ ਨਿਰੀਖਣ ਕਰ ਸਕਦੇ ਹਨ। ਨਿਰੀਖਣ ਦੌਰਾਨ ਕਿਸੇ ਕਿਸਮ ਦੀ ਕੋਈ ਅਣਗਹਿਲੀ ਪਾਈ ਗਈ ਤਾਂ ਬਿਨ੍ਹਾ ਕੋਈ ਨੋਟਿਸ ਦਿੱਤੇ ਜਾਰੀ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਕੀਤਾ ਜਾ ਸਕਦਾ ਹੈ।
- 7 ਡਾਇਰੈਕਟਰ ਜਰਨਲ ਸਕੂਲ ਸਿੱਖਿਆ ਵਿਭਾਗ ਪੰਜਾਬ ਸਟੇਟ ਪ੍ਰੋਜੈਕਟ ਸਰਵ ਸਿੱਖਿਆ ਅਭਿਆਨ ਦੇ ਪੱਤਰ ਨੰ: 75444 ਮਿਤੀ 06-11-2009 ਮੁਤਾਬਿਕ ਸਕੂਲ ਵਿਚ ਅੱਗ ਬੁਝਾਉਣ ਵਾਲੇ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿਚ ਰੱਖੇ ਜਾਣ ਕਿਸੇ ਵੀ ਅਣਸੁਖਾਂਵੀ ਦੁਰਘਟਨਾ ਦੀ ਸਾਰੀ ਜਿੰਮੇਵਾਰੀ ਸਬੰਧਤ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।
- 8 ਅਗਲੇ ਸਾਲ 2024-25 ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਕਰਾਉਣੀ ਯਕੀਨੀ ਬਣਾਈ ਜਾਵੇ।

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ,
ਮੋਗਾ।

Building Safety Report (PART-II)

NAME OF SCHOOL :-Akal Academy Bakarwala
(District- MOGA)

As per report of Sh, Jagsir Singh Junior Engineer on his visually inspection on dated 13-04-2023 the above mentioned School seems visually safe subject to the following observations an conditions.

1. The parameters to check the stability and safety of building such as structural Design Architectural Drawings ,Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test report of Material used and Quality control report are not available.
2. In Case any addition, alteration. Expansion and modification to this building are required/to be done, regarding this, inspections of undersigned may be arranged and obtained a certification after the completion from the undersigned.
3. In the case of building is affected flood or if there is any settlement of walls Foundation of roof etc. immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety if the building from all angles in spite of this report.
7. This report is for the the covered area of School building **32442.79**. sft which is submitted by the school is building as per drawing.
8. The building of the school is constructed as brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2023-2028 Rs. Fifty Thousand only With Merchant Reference No. 5764795 Dated 25-04-2023.
11. Fire safety Certificate is valid till 31.03-2024 and School will be responsible to get renewed fire safety Certificate within time limit.


Junior Engineer


Sub Divisional Engineer,
Provincial Sub Division,
PWD (B&R) Br Moga

14) Requirement for fire Protection Arrangements under NBC Part -IV

- (For Building height Less than 15metre) :
- a) Weather house Real provided. : Yes / No
- b) Weather down corner provided. : Yes / No
- c) Weather automatic sprinkler provided. : Yes / No
- d) Weather underground static water storage tank of Capacity 50,000Ltr.(It converted are excess 1600sqm) : Yes / No
- e) Weather over head tank of capacity 10,000 Ltr. Exists.(in case of house real) 20,000 Ltr. : Yes/ No
- f) Weather one electric and one diesel pump of 3 kg/ cum Pressure of capacity 1620 LPM.One electric pump of Capacity 180LPM exist near undery:ound static tank. : Yes/No
- g) Weather a pump 3 Kg /cum preasur& 450/500 LPM Exist near over head tank. : Yes/ No


PRINCIPAL
SCHOOL ACADEMY
BAKARWAL (MOGA)

PART -II

(To be filled by the S.D.E for PWD (B&R) Department)

- a) I have visited the above mentioned school on date 13-04-2023 And have been visually inspected it from all angles of safety and fined it fit for normal used as school buildings.
- b) In case and addition / alteration of expansion and modifications to this building is to be carried out the same be carried out under the supervision of a qualification Engineer and this certificate may be re-obtained after the completion from the undersigned.
- c) In case the building is affected by food , or if there is settlement of walls/ foundation of sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of t.l.e building.
- d) This building can be safety occupied for normal used upto (indicate upto which it can be used) Valid up to 31-03-2028


Sub Divisional Engineer,
Provincial Sub Division,
PWD (B&R) Br. Moga.