

Part -1

Performa For The Safety School Building

(To be filled by the Head of School / Institute)

1. Name of School Akal Academy Dhamot
2. Location V.P.O- Dhamot Kalan, Payal (Ldh.)
3. Plot Area 3.72 Acres
4. Plinth Area 7602 Ft²
5. Number of Storey 2 storey
6. Year of Construction of Building 2015
7. Supervision of the qualified Engineer,
The following details may be given:
 - (a) Name of Engineer En. Sanjeev Dha B.E.
 - (b) Address H.5A, Vijay Nagar New Delhi.
 - (c) Set of Structure drawing used in
The construction if available -Yes-
Arch., Ranjeet Singh & Associates 1206,
Surya Kiran Building 19 K.G. Marg
N.F.
 - (d) Name of the Architect
8. Whether the building has been constructed on the purpose of.
 - (a) School (Yes/No).... Yes
 - (b) Residential purpose and converted for use as school (Yes/No).... No
9. Materials used for Roof:
 - (a) R.C.C slabs (Yes/No).... R.C.C. slabs
 - (b) R.s joists and battens (Yes/No).... -
 - (c) Wooden joists and Battens (Yes/No).... -
10. Material used for walls:
 - (a) Mud Mortar (Yes/No).... -
 - (b) Cement Mortar (Yes/No).... Cement Mortar
 - (c) Plaster (i) Lime Mortar (Yes/No).... -
 - (ii) Cement Mortar (Yes/No).... Cement Mortar
11. Flooring:
 - (a) Conglomerate (Yes/No).... Yes
 - (b) Terrazzo (Yes/No).... No
 - (c) Brick Paving (Yes/No).... Bricks Floors
12. Detailed drawing indicating dimensions
Of the rooms along with size and location
Of doors and windows. Yes

Signature with stamp (Head of School)

Principal
Akal Academy
Dhamot

Part - II

(To be filled by S.D.E. of P.W.D. B & R Department)

No. - 411

Date: - 25.04.22

I have visited the above mentioned school on 23.04.2022 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls/foundations or caves of roof immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safety occupied for normal use to 31.03.2023 (indicate year up to which it can be used)


Sub Division Engineer
Construction Sub Division
PWD (B & R) Branch Doraha,

