

Part -1

Performa For The Safety School Building

(To be filled by the Head of School / Institute)

1. Name of School Akal Academy Dhamot
2. Location V.P.O. Dhamot, Taluk, Rayal (LDM)
3. Plot Area 3.22 Acres
4. Plinth Area 27,499.57 Sq. Ft.
5. Number of Storey 3 Storey
6. Year of Construction of Building 2015 - 2022
7. Supervision of the qualified Engineer,
The following details may be given:
 - (a) Name of Engineer Er. Sanjeev Daga B.E
 - (b) Address H. 5 A - Vijay Nagar New Delhi
 - (c) Set of Structure drawing used in
The construction if available Yes
 - (d) Name of the Architect Arch. Rajesh Singh & Associates
8. Whether the building has been constructed on the purpose of. Sanya Kiran Building 1206.
 - (a) School (Yes/No) Yes
 - (b) Residential purpose and converted for use as school (Yes/No) No
9. Materials used for Roof:
 - (a) R.C.C slabs No
 - (b) R.s joists and battens No
 - (c) Wooden joists and Battens No
10. Material used for walls:
 - (a) Mud Mortar (Yes/No) No
 - (b) Cement Mortar (Yes/No) Yes
 - (c) Plaster (i) Lime Mortar (Yes/No) Yes
(ii) Cement Mortar (Yes/No) Yes
11. Flooring:
 - (a) Conglomerate (Yes/No) Yes
 - (b) Terrazzo (Yes/No) No
 - (c) Brick Paving (Yes/No) Bricks Paving
12. Detailed drawing indicating dimensions
Of the rooms along with size and location
Of doors and windows. Yes

Headmistress
AKAL ACADEMY
Dhamot

Part-II

(To be filled by S.D.E of P.W.D B&R Department)

Building Safety Report

Name of School :- AKAL ACADEMY, DHAMOT

I have visited the above mentioned School building along with Sh. on dated 09/2/23 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and Certificate from Engineer in Charge for Construction are not available.
- In case of any addition, alteration of expansion and modification of this building are done; certificate may be re-obtained after completion from undersigned.
- In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- A separate certificate regard Electrical Work should be obtained from the competent authority.
- The owner of the building/Management is fully responsible regarding safety of building from all angels in spite of this report. 27500/-
- The covered area of the building is 27.449-57 1/2.
- This report is not valid for legal purpose.
- As per Government order no. 5/13/2018-3BR3/1294287/3 dated 10-08-2018 for issue of building safety certificate Para 2.0 (a), this certificate as requested by school authority is issued for period of 09 years up to 21/3/33

[Signature]
Junior Engineer

No! - 451

Dt: 14/02/2023

[Signature]
Sub Divisional Engineer,
Construction Sub Division No. 6
P.W.D. B & R Branch, Ludhiana.