

Performa for the Safety of School Building
Part I
(To be filled by the Head of the School / Institute)
2022-2023

1. Name of the School : AA Khichipur
2. Location : Teh:- Jalandhar Distt :-Jalandhar PB.
3. Plot Area : 10355.98 Sq m.=111430.34 Sq.Ft
4. Plinth Area : 1032.55 Sq.m = 11110.23 Sqft
5. No. of Storey's : G+1
6. Year of construction of Building : 2016
7. If the Building has been constructed Under the supervision of the qualified Engineer, the following details may be Given:

Name of the Engineer with : Er. Sanjeev Dua (B.E Civil)
Qualification : B.E CIVIL
Address of Engineer : 5A,Vijaynagar NewDelhi-110009

- a. Set of Structural Drawing used In the construction, if available.

a) Name & Address of Architect : Ar Jagvinder Kaur,
The KalgidharTrust
F-178 ,Phase 8A
Industrial Area ,Mohali.

b) With Qualification : A.I.I.A. CA/2017/81813

8. Whether the building has been Constructed for the purpose of
 - a. School : Yes
 - b. Residential purpose & converted : No
9. Material used for Roof
 - a. R.C.C. Slabs : Yes
 - b. R.S. joists & Batons : No
 - c. Wooden joist & Batons : No
10. Material used for walls
 - a. Mud Mortar : No
 - b. Cement Mortar : Yes
 - c. Plaster I) Lime Mortar : No
II) Cement Mortar : Yes
11. Flooring
 - a. Conglomerate :No
 - b. Terrazzo : No
 - c. Brick Paving : No
 - d. Cement Concrete : Yes
12. Of the room along with size and Location Of door window attached.

S. Kaur
12/4/22
Headmistress
Akai Academy
Khichipur

Jagvinder Kour
AR. JAGVINDER KOUR
THE KALGIDHAR TRUST
CA/2017/81813

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE

(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)

Name of the School: AKAL ACADEMY KHICHIPUR

- 1) This office Assistant Engineer/Junior Engineer visited the above mentioned School on 25-4-22 and have visually inspected it for its safety and find it fit for normal use as a school building.
- 2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or If there is settlement of walls/ foundation or sagging of roofs etc. Immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence It is expected that It can be safely occupied for normal use up to (Indicate year upto which It can be used)

This building is visually safe for year 2022-23
Ref. No. 253 (up to 31-3-23)

Dated 26-04-2022

[Signature]
Executive Engineer,
Provincial Division PWD,
B&R Br. Jalandhar Cantt.

[Signature]
Sub Division Engineer
Provincial Divn No. 2
PWD B&R Br. Jalandhar.