

ਦਫ਼ਤਰ : ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਨਸਾ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰ: 01652-232119

Email ID :- ken.mansa@gmail.com

ਪੱਤਰ ਨੰ..... 729

ਮਿਤੀ... 10/06/2021

ਵੱਲ,

ਹੈਡਮਾਸਟਰ, ਮਕਾਨ ਸਕੂਲ,  
ਫਾਫੜੇ ਭਾਇਕੇ,  
ਮਾਨਸਾ।

ਵਿਸ਼ਾ :- ਸਾਲ 2021-22 ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।  
ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ ਨਿਲ ਮਿਤੀ 05/04/2021

ਤੁਹਾਡੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਇੰਜੀਨੀਅਰ ਇੰਚਾਰਜ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ।  
ਨਿਰੀਖਣ ਦੌਰਾਨ ਪਾਇਆ ਗਿਆ ਕਿ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ  
ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ 31/03/2022 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ  
ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।  
ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ ਅਤੇ ਨਕਸ਼ਾ।

  
ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,  
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਮਾਨਸਾ।

# AKAL ACADEMY

English Medium, Day Boarding,  
Co-Educational Public School

01652-283103

e-mail : [aaphaphrebhaike@akalacademy.ac.in](mailto:aaphaphrebhaike@akalacademy.ac.in)

Phaphre Bhai Ke, V PO Bhai Behlo Phephre Bhai Ke,  
Tehsil & Distt. Mansa (Punjab)-151502  
Managed by : The Kalgidhar Trust, Baru Sahib(HP)

Date: 05/04/2021

ਵੱਲ :-

ਪ੍ਰਿੰਸੀਪਲ

ਅਕਾਲ ਅਕੈਡਮੀ

ਫਫੜੇ ਭਾਈਕੇ, ਮਾਨਸਾ

ਵੱਲ :-

ਦਫਤਰ

ਮਾਨਸਾ ।

ਵਿਸ਼ਾ :- ਬਿਲਡਿੰਗ ਦਾ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਸ੍ਰੀ ਮਾਨ ਜੀ,

ਬੇਨਤੀ ਹੈ ਕਿ ਅਕਾਲ ਅਕੈਡਮੀ ਫਫੜੇ ਭਾਈਕੇ ਸਕੂਲ ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸਰਟੀਫਿਕੇਟ ਬਣਾਉਣਾ ਹੈ।  
ਤਾਂ ਕਿ ਅਸੀਂ ਆਪ ਜੀ ਵੱਲੋਂ ਸਮੇਂ ਸਮੇਂ ਸਿਰ ਜੋ ਨਵੀਆਂ ਹਦਾਇਤਾਂ ਜਾਰੀ ਹੁੰਦੀਆਂ ਹਨ, ਉਹਨਾਂ ਦੀ ਪਾਲਣਾ  
ਕਰਦੇ ਰਹੀਏ। ਸੋ ਬੇਨਤੀ ਹੈ ਬਿਲਡਿੰਗ ਸਰਟੀਫਿਕੇਟ ਦਾ ਸਰਟੀਫਿਕੇਟ (2021-22) ਦਾ ਜਾਰੀ ਕੀਤਾ ਜਾਵੇ।

ਧੰਨਵਾਦ ਸਹਿਤ।

  
Headmistress  
Akai Academy Phaphre Bhai Ke  
(Mansa) 05/04/2021

ਹੈਡਮਿਸਟਰੈਸ

ਅਕਾਲ ਅਕੈਡਮੀ

ਫਫੜੇ ਭਾਈਕੇ, ਮਾਨਸਾ।

Performa for the Safety of School Building  
Part 1  
(To be filled by the Head of the School / Institute)  
2021-2022

1. Name of the School : AA Phaphre Bhai ke
2. Location : Teh. :- Mansa ,Distt :- Mansar.(PB).
3. Plot Area : 15598.79Sq.m .
4. Plinth Area : 795.19 Sq m .
5. No. of Storey's : G+2 Existing
6. Year of construction of Building : 2009
7. If the Building has been constructed Under the supervision of the qualified Engineer, the following details may be Given:

- Name of the Engineer with Qualification : Er. Sanjeev Dua (B.E Civil )  
Address of Engineer : B.E CIVIL  
: 5A, Vijaynagar NewDelhi-110009
- a. Set of Structural Drawing used In the construction, if available. :
- a) Name & Address of Architect : Ar Jagvinder Kaur,  
The KalgidharTrust  
C-120 ,Phase 8  
Industrial Area ,Mohali.
- b) :
- b. With Qualification : A.I.I.A , CA/2017/81813.(Registration no.)
8. Whether the building has been Constructed for the purpose of
- a. School : Yes
  - b. Residential purpose & converted : No
9. Material used for Roof
- a. R.C.C. Slabs : Yes
  - b. R.S. joists & Batons : No
  - c. Wooden joist & Batons : No
10. Material used for walls
- a. Mud Mortar : No
  - b. Cement Mortar : Yes
  - c. Plaster I) Lime Mortar : No  
II) Cement Mortar : Yes
11. Flooring
- a. Conglomerate :No
  - b. Terrazzo : No
  - c. Brick Paving : No
  - d. Cement Concrete : Yes
12. Of the room along with size and Location Of door window attached.

*Jagvinder Kaur*  
AR. JAGVINDER KOUR  
THE KALGIDHAR TRUST  
CA/2017/81813

*Jagvinder Kaur*  
Headmistress 05/04/2021  
Akai Academy Phaphre Bhai ke  
(Mansa)

## Building Safety Report

NAME OF SCHOOL:- ARAJ ACADEMY PHAPRE BHAIKE

(District- MANSA)

As per report of Veeraj Patil Assistant/Junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions.

1. The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building 795.10 X 3 5041 25668.08 which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2021-22

As per visually inspection as reported by the concerned Assistant/Junior Engineer the above building may be used for normal use for One year up to 31.3.22 Subject to the above conditions.

Veeraj Patil  
Assistant/Junior Engineer

Sub Divisional Engineer  
Prov. Sub Divin. P.W.D. B&R No.:-1  
MANSA  
74